


G2 SPEED REDUCTION



5001




No.	Description	Quantity	No.	Description	Quantity
1	Screw M8 x 20	4	12	Gasket	3
2	Nut M8	8	13	Socket cap screw M8 x 35	8
3	Cover	1	14	Oil level plug 3/8"	1
4	Bearing type 6010	2	15	Oil filling cap 3/8"	1
5	Gasket	1	16	Bearing type 6007	2
6	Hollow shaft Ø35	1	17	Pinion gear	1
7	Snap ring Ø50	2	18	Key 12 x 8	1
8	Ring gear	1	19	Peg 6 x 12	2
9	Sealing ring Ø50 x 65 x 8	2	20	Sealing ring Ø35 x 52 x 7	1
10	Housing	1	21	Flange	1
11	Oil drain plug 3/8"	1			


TECHNICAL SHEET

Input torque (Nm)	Output torque (Nm)	Input speed (r/min)	Transmission ratio	Output speed (r/min)	Power (Kw)	Weight (Kg)
130	196	300	1.5	200	10	6
88	176	400	2	200	10	6
77	192	500	2.5	200	10	6
67	200	600	3	200	10	6
63	214	700	3.5	200	10	6
49	186	760	3.8	200	10	6


THREE VIEWS



SHAFT



MOUNTING POSITIONS



HOW TO ORDER

